Inspection Date: July 13, 2010

Page 1 of 2 M/023/0023



# State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

## **Inspection Report Minerals Regulatory Program** Date:

Reviewed:

July 14, 2010				
Mine Name: Levan Henry	Permit Number: M/023/0023			
Operator Name: Sunroc	Inspection Date: 07/13/2010			
Inspector(s): Wayne Western	<b>Time</b> : 1:10 – 1:30 pm			
Other Participants: none	Mine Status: ACT			

Elements of Inspection	Evaluated	Comment	Enforcement
Permits, Revisions, Transfer, Bonds	$\boxtimes$		
Public Safety (shafts, adits, trash, signs, highwalls)	$\boxtimes$		
Protection of Drainages / Erosion Control			
Deleterious Material	$\boxtimes$	$\boxtimes$	7 72
Roads (maintenance, surfacing, dust control, safety)			
Concurrent Reclamation			
Backfilling/Grading (trenches, pits, roads, highwalls, hafts, drill holes)			
Vater Impoundments			
oils			
Re-vegetation			
air Quality			
Other			
0 2 3 1 1	ermits, Revisions, Transfer, Bonds ublic Safety (shafts, adits, trash, signs, highwalls) rotection of Drainages / Erosion Control releterious Material oads (maintenance, surfacing, dust control, safety) oncurrent Reclamation ackfilling/Grading (trenches, pits, roads, highwalls, nafts, drill holes) //ater Impoundments oils e-vegetation ir Quality	ermits, Revisions, Transfer, Bonds  ublic Safety (shafts, adits, trash, signs, highwalls)  rotection of Drainages / Erosion Control  eleterious Material  oads (maintenance, surfacing, dust control, safety)  oncurrent Reclamation  ackfilling/Grading (trenches, pits, roads, highwalls, hafts, drill holes)  //ater Impoundments  oils  e-vegetation  ir Quality	ermits, Revisions, Transfer, Bonds  ublic Safety (shafts, adits, trash, signs, highwalls)  rotection of Drainages / Erosion Control  eleterious Material  oads (maintenance, surfacing, dust control, safety)  oncurrent Reclamation  ackfilling/Grading (trenches, pits, roads, highwalls, hafts, drill holes)  //ater Impoundments  oils  e-vegetation  ir Quality

#### **Purpose of Inspection:**

This was a routine inspection.

#### **Inspection Summary:**

The site was in good shape. No signs of erosion problems. The camera was not working not pictures were taken. The bond is for \$99,735 and due for escalation in 2012.

### **Conclusions and Recommendations:**

The Division should continue to monitor the site.

### **Directions:**

The turn off is approximately 2.5 south of Levan.

Inspection Date: July 13, 2010

Page 2 of 2 M/023/0023

Inspector's Signature

WHW

Tony Christofferson

Agency - Uinta National Forest / Fee

 $O: \label{lem:linspections} INSP\_M0230023\_07132010. doc$ 

Vague Wee long